

# KA-505 Mobile Base (6 casters)

## User Manual

### Brief Introduction

The product is used with a cage bank which has 2 KA-505L cages on the bottom.

### Parts List



**4 long-side steel bars, 2 short-side steel bars, 1 short reinforcing steel bar;**

Note: For 4 long-side steel bars,  
the ends with 4 holes should be with the short-side steel bars;  
and the ends with 2 holes should be with short reinforcing steel bar.



**4 casters with brakes, 2 casters without brakes;**

**24 M8\*16 screws;**

Note: The casters with brakes should be on the corner.

### Assembly




1. Array the steel bars on the ground. (See the figure above)



2. Start with a corner caster. Align the holes of the long-side bar, short-side bar and a caster (with a brake). (See the figure above)

Note: The long-side bar must be put on the top of the short-side bar.



3. Fix with a screw, nut and washer. (See the figure above)



4. Four screws are used to fix the castor to the corner. (See the figure above)



5. Then install a castor in the middle. Align the holes of the long-side bar, short reinforcing steel bar and a castor (without a brake). (See the figure above)  
Note: The long-side bar must be put on the top of the short reinforcing steel bar.



6. Four screws are used to fix the caster in the middle. (See the figure above)
7. One by one install the other casters.



8. The mobile base is completed. (See the figure above)